



WARATAH

Logrite® REPAIRS



Save thousands \$\$\$\$

Don't replace your Logrite® 750, fix it !

An unreadable screen is a common issue with the Logrite® display.

TK SYSTEMS have had these LCD screens re-manufactured to a much higher standard than the original ones and we are now able to offer a repair service for your faulty Logrite® displays.

Don't hesitate, contact us now to arrange your repair or obtain an immediate quote.

The cost saving will be worth it !

www.tksystems.com.au

inquiries@tksystems.com.au

Phone: +61 3 5962 5211

Fax: +61 3 5962 5291